

Dexterity

emergency and rescue teams.

Keep in cool, dry place, away from heat sources


Clean all its parts on a regular basis with a moist

cloth and soapy water or non-aggressive

detergent. Do not use any solvents.

Storage and cleaning

and direct sunlight.



Once you become aware of a damage, you

should immediately replace it.

EC Standards

EN 397 CE

EN 50365