



as PPE Cat. II.

Category	Colours	Available Sizes
II	Grey	35-38
Quantity/Carton	Important Information	Recommended for
10	The footwear should be stored in a cool dry place, far from heat sources and direct light. Make sure footwear is in good condition, before use. If the shoes are damaged, replace them.	Construction, Agricultural sector and Forestry, Light and heavy mechanical industry, Metallurgic industry, Handling and Logistics, Cleaners, Maintenance technicians and Installers.
Dexterity	EC Standards	Storage and cleaning
	EN 20345	Clean the footwear with a soft brush and water.
	Safety Class:S1 SRC	