

EN 1731-F

TECH	INICAL	SHEET

Wholly-owned subsidiary Via dei Fornaciai, 9 - San 06081 Assisi - Perugia - I	ita Maria degli Angeli	VAT Nr. IT 03359340548 Viale Europa 74 20090 Cusago Milano Tel. +39 02.90394575 (R.A.) Fax +39 02.90394441	export@sirsafety.com www.sirsafety.com	COMPANY WITH QUALITY SYSTEM CERTIFIED BY DAV GL = ISO 9001 =
Name: Polycarbon	ate Visor for Electric Ar	c Code: 38320	Head Protection - MSA	A
Description				
circuit electric arc, m The product is desig	nolten metal and hot solid	comply with the essential		
	quirements of Directive 8 E Cat. II.	9/686/EEC.		
It is classified as PP		9/686/EEC.	Available Sizes	
It is classified as PP	È Cat. II.	9/686/EEC.	Available Sizes Unica	
It is classified as PP Category II	È Cat. II.			
It is classified as PP Category II	É Cat. II. Colours Transparent Important Information	s in good condition, before	Unica Recommended for	es, short circuit electric arc, olids.
It is classified as PP Category II Quantity/Carton 10	È Cat. II. Colours Transparent Important Information Make sure the visor is	s in good condition, before	Unica Recommended for Protection from splashe	
It is classified as PP Category II Quantity/Carton	È Cat. II. Colours Transparent Important Information Make sure the visor is use. If the visor is dat	s in good condition, before	Unica Recommended for Protection from splasher molten metal and hot so Storage and cleaning Keep in a cool dry place	olids.
It is classified as PP Category II Quantity/Carton 10	È Cat. II. Colours Transparent Important Information Make sure the visor is use. If the visor is dat EC Standards	s in good condition, before maged, replace it.	Unica Recommended for Protection from splasher molten metal and hot so Storage and cleaning	olids.
It is classified as PP Category II Quantity/Carton 10	É Cat. II. Colours Transparent Important Information Make sure the visor is use. If the visor is dan EC Standards EN 166 CE	s in good condition, before maged, replace it.	Unica Recommended for Protection from splasher molten metal and hot so Storage and cleaning Keep in a cool dry place	olids.