

Sir Safety System S.p.A. Single-member company
Wholly-owned subsidiary of Sir Holding Srl
Via dei Fornaciai, 9 - Santa Maria degli Angeli
06081 Assisi - Perugia - Italy
Tel.+39 075.8043737 (R.A.) - Fax +39 075.8048686

VAT Nr. IT 03359340548
Viale Europa 74
20090 Cusago Milano
Tel. +39 02.90394575 (R.A.)
Fax +39 02.90394441

export@sirsafety.com
www.sirsafety.com

COMPANY WITH
QUALITY SYSTEM
CERTIFIED BY DNV GL
= ISO 9001 =



Name: Gas Alert BW CLIP CO - 2 Years	Code: 81518N	Gas Detectors - BW
---	---------------------	---------------------------

Description

The gas detector BW Clip CO is ideal for those who perform activities in hazardous environments. It operates up to three years maintenance-free. Just turn on the device and it runs continuously - no need for calibration, sensor replacement, battery replacement or battery charging. With BW Clip for CO - 2 year it is possible to put the device in hibernation mode, by placing it in an appropriate housing when not in use for more than a week, thus it extends its life by that period of time.

It features:

- Maintenance-free: no sensor or battery changes necessary.
- Compact, lightweight design with one-button operation.
- Designed to withstand harsh environments and extreme temperatures.
- Automated self-test of battery, sensor and electronics.
- Wide-angle flash, which alerts simultaneously with audible and vibrating alarm.
- Automatic logging of the 35 most recent gas events and bump test results.

Compact 4,1 x 5,0 x 8,7 cm

Lightweight: 92 g

Humidity:5% - 95% UR (non-condensing)

Visual, vibrating and acoustic alarm (95 dB); low/high.

Test: Activated detectors automatically perform one internal diagnostic test every 24 hours.

Ingress Protection: IP 66/67



Category III	Colours Yellow	Available Sizes
Quantity/Carton 1	Important Information Make sure the product is in good condition, undamaged and clean before use. Once you become aware of a damage, you should immediately replace it.	Recommended for Suitable to detect the presence of Carbon Monoxide.
Dexterity	EC Standards	Storage and cleaning Keep in a cool dry place, far from heat sources.